



Impala Platinum Holdings

Managed Tailings Dams

FEBRUARY 2021

Tailings Facilities



IMPALA

Disclosure Requirements	Impala Rustenburg
Tailings Facility Name and Identifier	Tailings Dam 3 & 4 (Combined Tailings Facility) Phase 1
Location	25°31'9.06"S; 27°14'16.53"E

1 Company name	Impala Platinum	11 How are the tailings stored? (conventional, thickened, paste, dry stack, other)	Conventional
2 Company's membership with ICMM or other international industry body.	No	12 Do the contents of the TMF include toxic materials?	No
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?	Yes	For a decommissioned facility	
a. Are audit reports (external and/or internal) shared with the board?	Yes (Bi-annual by SRK and Annual by Knight Piesold)	13 Year construction was started.	N/A
4 Number of TMFs owned by the company	Tailings Dam 3 & 4 (Combined Tailings Facility)	14 Last year that material was added to the facility.	N/A
a. In construction?	Yes	15 Year of decommissioning.	N/A
b. In operation?	Yes	a. Was it capped, crowned and/or was another method used to reduce water infiltration?	N/A
c. Closed/decommissioned?	No	b. Frequency of internal/external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	N/A
d. In operation/closed but not decommissioned/decommissioned?	In operation	For an operational and closed facilities	
For Each TMF		16 Year construction was started.	1978
5 Mine name	Impala Platinum	17 Current tailings production (ktpy).	11 million tons per year
6 Location (Country/State/Municipality)	South Africa / North West / Phokeng	18 Current density/water content of the tailings being deposited.	1.48 t/m ³
7 TMF name or designation	Rustenburg Impala Platinum Mine Tailings Dam 3 & 4 (Combined Tailings Facility)	19 Expected remaining years of operations.	30 years
8 Location of Facility (lat/long or position relative to the main mine facilities)	Latitude 25°31'9.06"S / Longitude 27°14'16.53"E	TMF Monitoring	
9 The types of commodities being mined	Two economic orebodies are currently mined, namely the Merensky economic horizon and the UG2 Chromitite seam. From this mining activity, refined platinum, plus other Platinum Group Metals (PGMs) are produced	20 Frequency of internal inspections (if any)	Daily inspections by the tailings dam operator. Weekly combined inspections by the Mine and tailings dam operator.
10 What are the main methods used in the processing of the ore prior to deposition.	Ore consists of Merensky and UG2. Ore processing entails crushing, milling, flotation and tailings handling facilities. Flotation consists of various stages producing a PGMs concentrate which is then further processed at the Smelter. The tailings stream comprises materials from five main sources, namely the Merensky Plant, the UG2 Plant, the Mill Float 2 (MF2) Plant, the Slag Plant and the Tailings Recovery Plant (TRP). Once these tailings streams have gone through the Tailings Scavenger Plant (TSP) and the Impala Chrome Plant, the remaining tailings is disposed of onto Tailings Dam No.4 in a slurry by a spigot system around the deposition area.	a. Date of last internal inspection including outcome.	15.01.2021 - No items of concern noted.
		21 Is there a requirement for external inspections?	Yes
		a. Frequency of external inspections.	Monthly, quarterly and annually
		b. Name of external firm that performs the inspection.	SRK and Knight Piesold
		c. Date of last external inspection including outcome.	Annual audit Decemeber 2020 - No major concerns ; Monthly Jan 2021
		22 If there is an external rating system (i.e. local regulator),	SANS 10286:1998
		a. What is the risk rating for the TMF?	HIGH hazard facility (SANS 10286:1998)



IMPALA

Disclosure Requirements	Impala Rustenburg
Tailings Facility Name and Identifier	Tailings Dam 3 & 4 (Combined Tailings Facility) Phase 1
Location	25°31'9.06"S; 27°14'16.53"E

For TMF with embankment retaining structures		32. Do current neighboring mining operations include blasting?	Only internal properties, Operational Shafts (11#, 11C# and 10 #)
Design		a. If yes, distance of the TMF to the mining operations.	TSF to 11#: 2.4km center to center & 450m from side wall /TSF to 11C #: 2.27km center to center & 1km from side wall / TSF to 10#: 2.07km center to center & 420m from side wall
23. Type of construction	Upstream	33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	Done as per Biodiversity Management procedure (IMP - ES33)
a. Upstream, downstream, centerline, other;	Upstream		
b. Is it constructed on flat ground or on a slope?	Gently sloping land		
c. Does it include a spillway or other structure to mitigate overtopping?	Yes, penstock tower		
d. Does it include an overdrain and/or underdrain system?	Underdrain	34. Nearest critical infrastructure downstream from the facility, including nearby TMFs.	Site offices 200m, 10# 250m,TSF to 11#: 2.4km center to center & 450m from side wall /TSF to 11C #: 2.27km center to center & 1km from side wall / TSF to 10#: 2.07km center to center & 420m from side wall
24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/ CDA), ANCOLD, ICOLD or others?	SANS 10286:1998		
25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	Section P4 = 1.599 (minimum) and Section P19 = 1.883 (maximum), (Effective Stress Analysis). Undrained analysis to be undertaken in 2021.		
26. Current dimensions of main structure, including height, upstream slope and downstream slope.	Maximum height 85.5m. Overall outer slope 1:3, interbench slope 1:1.5, natural ground slope 1:61		
27. Planned final dimensions of main structure.	Planned final height 144.6m.	Additional comments incl. mitigants	
28. Current volume of tailings facility (m ³ , tonnes, etc.).	327,645,481.3 m ³	Daily inspections by the tailings dam operator. Weekly combined inspections by the Mine and tailings dam operator. Monthly combined inspections by the Mine, consultant, tailings dam operator and the private consultant. Annual 3rd party audits. Annual dam inspections. Annual aerial inspections. Annual dam movement monitoring surveys. Annual drains inspection. Annual camera inspections of both penstock outfall pipelines. Annual inspection of the trough unit systems. Camera inspection of problematic drains as and when required. Five yearly dam safety inspections. Fraser Alexander is the daily tailings dam operator together with the mine management. SRK is the geotechnical engineering consultant who provide technical advice to the operation of the facility. Knight Piezold act as 3rd party/private consultant.	
29. Planned final volume of tailings facility.	361,019,481.3 m ³ Forecast Impoundment volume at January 2024		
Surrounding environment analysis			
30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	No		
31. Seismicity rating of the TMF's location.	V (Modified Mercalli Scale) = Richter scale magnitude of 4 to 5.		



IMPALA

Disclosure Requirements	Impala Rustenburg
Tailings Facility Name and Identifier	Tailings Dam 1 & 2 (Combined Tailings Facility) Phase 1
Location	25°31'12.32"S / 27°11'56.73"E

1 Company name	Impala Platinum	10 What are the main methods used in the processing of the ore prior to deposition.	Ore consists of Merensky and UG2. Ore processing entails crushing, milling, flotation and tailings handling facilities. Flotation consists of various stages producing a PGMs concentrate which is then further processed at the Smelter. The tailings stream comprises materials from five main sources, namely the Merensky Plant, the UG2 Plant, the Mill Float 2 (MF2) Plant, the Slag Plant and the Tailings Recovery Plant (TRP). Once these tailings streams have gone through the Tailings Scavenger Plant (TSP) and the Impala Chrome Plant, the remaining tailings is disposed of onto Tailings Dam No.4 in a slurry by a spigot system around the deposition area.
2 Company's membership with ICMM or other international industry body.	No		
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?	Yes		
a. Are audit reports (external and/or internal) shared with the board?	Yes (Bi-annual by SRK and Annual by Knight Piesold)		
4 Number of TMFs owned by the company	Tailings Dam 1 & 2(Combined Tailings Facility)		
a. In construction?	Reprocessing		
b. In operation?	Reprocessing		
c. Closed/decommissioned?	Reprocessing		
d. In operation/closed but not decommissioned/decommissioned?	Reprocessing		
For Each TMF			
5 Mine name	Impala Platinum	12 Do the contents of the TMF include toxic materials?	No
6 Location (Country/State/ Municipality)	South Africa / North West / Phokeng	For a decommissioned facility	
7 TMF name or designation	Rustenburg Impala Platinum Mine Tailings Dam 1 & 2	13 Year construction was started.	1968
8 Location of Facility (lat/long or position relative to the main mine facilities)	Latitude 25°31'12.32"S / Longitude 27°11'56.73"E	14 Last year that material was added to the facility.	1981
9 The types of commodities being mined	Two economic orebodies are currently mined, namely the Merensky economic horizon and the UG2 Chromitite seam. From this mining activity, refined platinum, plus other Platinum Group Metals (PGMs) are produced	15 Year of decommissioning.	1981
		a. Was it capped, crowned and/or was another method used to reduce water infiltration?	Vegetated
		b. Frequency of internal/ external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	Monthly
		For an operational and closed facilities	
		16 Year construction was started.	1968
		17 Current tailings production (ktpy).	NA (5000 tons per day being reprocessed)
		18 Current density/water content of the tailings being deposited.	NA
		19 Expected remaining years of operations.	



IMPALA

Disclosure Requirements	Impala Rustenburg
Tailings Facility Name and Identifier	Tailings Dam 1 & 2 (Combined Tailings Facility) Phase 1
Location	25°31'12.32"S / 27°11'56.73"E

TMF Monitoring			
20 Frequency of internal inspections (if any)	Daily inspections by the tailings dam operator. Weekly combined inspections by the Mine and tailings dam operator.	26. Current dimensions of main structure, including height, upstream slope and downstream slope.	Maximum height 26m. Overall outer slope 1:3 to 1:3.5
a. Date of last internal inspection including outcome.	15.01.2021 - No items of concern noted.	27. Planned final dimensions of main structure.	NA
21 Is there a requirement for external inspections?	Yes	28. Current volume of tailings facility (m ³ , tonnes, etc.).	28,470,519.9 m ³
a. Frequency of external inspections.	Monthly, quarterly and annually	29. Planned final volume of tailings facility.	Planned to reprocess entire TMF
b. Name of external firm that performs the inspection.	SRK and Knight Piesold	Surrounding environment analysis	
c. Date of last external inspection including outcome.	Annual audit Decemeber 2020 - No major concerns ; Monthly Jan 2021	30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	No
22 If there is an external rating system (i.e. local regulator),	SANS 10286:1998	31. Seismicity rating of the TMF's location.	V (Modified Mercalli Scale) = Richter scale magnitude of 4 to 5.
a. What is the risk rating for the TMF?	MEDIUM Hazard facility (SANS 10286:1998)	32. Do current neighboring mining operations include blasting?	Only internal properties, Operational Shafts (11# and 11C#)
For TMF with embankment retaining structures		a. If yes, distance of the TMF to the mining operations.	TSF to 11#: 2.5km center to center & 1.5km from side wall / TSF to 11C #: 4.27km center to center & 3.38km from side wall
Design		33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	Done as per Biodiversity Management procedure (IMP - ES33)
23 Type of construction		34. Nearest critical infrastructure downstream from the facility, including nearby TMFs.	Community, 100m from TMF,TSF to 11#: 2.5km center to center & 1.5km from side wall /TSF to 11C #: 4.27km center to center & 3.38km from side wall
a. Upstream, downstream, centerline, other;	Reprocessing. Original construction was upstream.	Additional comments incl. mitigants	
b. Is it constructed on flat ground or on a slope?	Gently sloping land	COP requirement is the following (a) Professional Engineer to oversee risk monitoring (b) Professional Engineer to audit the tailings dam annually. Remining activities being monitored as follows: Daily inspections by the tailings dam operator. Weekly combined inspections by the Mine and tailings dam operator. Monthly combined inspections by the Mine, consultant, tailings dam operator and the private consultant. Annual aerial inspections.	
c. Does it include a spillway or other structure to mitigate overtopping?	Yes, large diameter pipes		
d. Does it include an overdrain and/or underdrain system?	No		
24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/CDA), ANCOLD, ICOLD or others?	Mine tailings disposal was largely unregulated in 1967. Rudimentary guidance was available on tailings storage construction in South Africa which was based on research carried out under the direction of J.E. Jennings and issued as an internal document by the Chamber of Mines in 1959		
25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	No recent assessments		



MARULA

Disclosure Requirements	Marula
Tailings Facility Name and Identifier	Tailings Dam 1 & 2
Location	TD1 24°30'40.99"S, 30° 6'29.96"E TD2 24°31'0.94"S, 30° 6'16.00"E


1 Company name	Marula Platinum	b. Frequency of internal/ external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	N/A
2 Company's membership with ICMM or other international industry body.	No	For an operational and closed facilities	
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?	Yes	16 Year construction was started.	First deposition - 2004
a. Are audit reports (external and/ or internal) shared with the board?	Yes	17 Current tailings production (ktpy).	20 Tailings Dam 2 (TD2) 1850
4 Number of TMFs owned by the company	2	18 Current density/water content of the tailings being deposited.	1,5
a. In construction?	1	19 Expected remaining years of operations.	<1 year
b. In operation?	1	TMF Monitoring	
c. Closed/decommissioned?	0	20 Frequency of internal inspections (if any)	Weekly
d. In operation/closed but not decommissioned/ decommissioned?	0	a. Date of last internal inspection including outcome.	Stable Operation
For Each TMF		21 Is there a requirement for external inspections?	Yes
5 Mine name	Marula Platinum Mine	a. Frequency of external inspections.	Monthly
6 Location (Country/State/ Municipality)	South Africa / Limpopo Province / Fetakgomo Greater Tubatse Municipality	b. Name of external firm that performs the inspection.	SRK Consulting
7 TMF name or designation	a. Tailings Dam 1 (TD1) - in operation, b. Tailings Dam 2 (TD2) - under construction	c. Date of last external inspection including outcome.	Dec-21
8 Location of Facility (lat/long or position relative to the main mine facilities)	a. Tailings Dam 1 (TD1) - 24°30'40.99"S, 30° 6'29.96"E b. Tailings Dam 2 (TD2) - 24°31'0.94"S, 30° 6'16.00"E	22 If there is an external rating system (i.e. local regulator),	Yes (SANS10286)
9 The types of commodities being mined	Platinum Group Metals and Chrome	a. What is the risk rating for the TMF?	High Risk
10 What are the main methods used in the processing of the ore prior to deposition.	Milling, Flotation	For TMF with embankment retaining structures	
11 How are the tailings stored? (conventional, thickened, paste, dry stack, other)	Ring Dyke Spigotted	Design	
12 Do the contents of the TMF include toxic materials?	No	23 Type of construction	
For a decommissioned facility		a. Upstream, downstream, centerline, other;	Upstream
13 Year construction was started.	N/A	b. Is it constructed on flat ground or on a slope?	Gentle Slope, Considered Flat
14 Last year that material was added to the facility.	N/A	c. Does it include a spillway or other structure to mitigate overtopping?	2 x Penstocks
15 Year of decommissioning.	N/A	d. Does it include an overdrain and/or underdrain system?	Underdrain System Included
a. Was it capped, crowned and/ or was another method used to reduce water infiltration?	N/A		



MARULA

Disclosure Requirements	Marula
Tailings Facility Name and Identifier	Tailings Dam 1 & 2
Location	TD1 24°30'40.99"S, 30° 6'29.96"E TD2 24°31'0.94"S, 30° 6'16.00"E

24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/CDA), ANCOLD, ICOLD or others?		32. Do current neighboring mining operations include blasting?	Yes
25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	>1.5	a. If yes, distance of the TMF to the mining operations.	±2km
26. Current dimensions of main structure, including height, upstream slope and downstream slope.	40.1m Height, 1:3 Side slopes	33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	a. Madikane community (±500 PAR in the Zone of influence) b. Moopetsi River (±500m downstream) c. Increased frequency of monitoring, against what is required. d. Trigger Action Response Plan (TARP) implemented. e. Dam Break Analysis planned for 2021
27. Planned final dimensions of main structure.	42m Final Height, 1:3 Sideslopes	34. Nearest critical infrastructure downstream from the facility, including nearby TMFs.	a. TD2 Abuts TD1 for improved stability b. Driekop Shaft c. Clapham Shaft
28. Current volume of tailings facility (m ³ , tonnes, etc.).	13.7 million m ³	Additional comments incl. mitigants	
29. Planned final volume of tailings facility.	14.2 million m ³		
Surrounding environment analysis			
30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	Yes		
31. Seismicity rating of the TMF's location.	a. Seismicity: Falls naturally in a zone of peak horizontal acceleration of less than 50 cm/s ² – mining at Marula and surrounds are not affecting this (mainly due to shallower mining of UG2) (The probability of such ground movement (s) being exceeded at least once in fifty yrs is 10%)		



ZIMPLATS

Disclosure Requirements	Zimplats
Tailings Facility Name and Identifier	Selous Metallurgical Complex
Location	18° 0' 36", 30° 4' 34"

1 Company name	Zimplats	For an operational and closed facilities	
2 Company's membership with ICMM or other international industry body.	No	16 Year construction was started.	1995
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?	Yes	17 Current tailings production (ktpy).	2 200ktpy
a. Are audit reports (external and/or internal) shared with the board?	Yes	18 Current density/water content of the tailings being deposited.	1.5-1.6Kg/L
4 Number of TMFs owned by the company		19 Expected remaining years of operations.	5 years
a. In construction?	Nil	TMF Monitoring	
b. In operation?	2	20 Frequency of internal inspections (if any)	Daily
c. Closed/decommissioned?	Nil	a. Date of last internal inspection including outcome.	Current date. No major threatening issues.
d. In operation/closed but not decommissioned/decommissioned?	Nil	21 Is there a requirement for external inspections?	Yes
For Each TMF		a. Frequency of external inspections.	Every 4 months by TSF designers and every two years by independent third party
5 Mine name	Selous Metallurgical Complex (SMC)	b. Name of external firm that performs the inspection.	SRK and appointed third parties. Last third party was conducted by John Wates in October 2019
6 Location (Country/State/Municipality)	Zimbabwe/Mashonaland West Province/Selous	c. Date of last external inspection including outcome.	27 November 2020 by SRK TSF designers
7 TMF name or designation	SMC	22 If there is an external rating system (i.e. local regulator),	No external rating but internal rating
8 Location of Facility (lat/long or position relative to the main mine facilities)	18° 0' 36", 30° 4' 34"	a. What is the risk rating for the TMF?	Not applicable
9 The types of commodities being mined	Platinum Group Metals	For TMF with embankment retaining structures	
10 What are the main methods used in the processing of the ore prior to deposition.	Milling and Flotation	Design	
11 How are the tailings stored? (conventional, thickened, paste, dry stack, other)	Conventional	23 Type of construction	
12 Do the contents of the TMF include toxic materials?	No	a. Upstream, downstream, centerline, other;	Upstream
For a decommissioned facility		b. Is it constructed on flat ground or on a slope?	Slightly sloppy ground
13 Year construction was started.	N/A	c. Does it include a spillway or other structure to mitigate overtopping?	Berms on the outer paddocks to mitigate overtopping
14 Last year that material was added to the facility.	N/A	d. Does it include an overdrain and/or underdrain system?	Underdrains included
15 Year of decommissioning.	N/A	24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/CDA), ANCOLD, ICOLD or others?	SANS 10286
a. Was it capped, crowned and/or was another method used to reduce water infiltration?	N/A		
b. Frequency of internal/external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	N/A		



ZIMPLATS

Disclosure Requirements	Zimplats
Tailings Facility Name and Identifier	Sellous Metallurgical Complex
Location	18° 0' 36", 30° 4' 34"

25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	Drained FoS 1.86 (target ≥ 1.5) and undrained FoS 1.54 (target ≥ 1.3)	33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	7 families residing in the TSF zone of influence
26. Current dimensions of main structure, including height, upstream slope and downstream slope.	35m from lowest natural ground level		
27. Planned final dimensions of main structure.	110ha (existing) and 203ha proposed combined abutting TSFs		
28. Current volume of tailings facility (m³, tonnes, etc.).	39 million tonnes and 24.4m ³	34. Nearest critical infrastructure downstream from the facility, including nearby TMFs.	Community homesteads and three bridges
29. Planned final volume of tailings facility.	37.5m ³ (portion to existing TSF factoring in proposal to increase TSF height to 1298mamsl)		
Additional comments incl. mitigants			
The existing TSF extension zone of influence resides community. Zimplats has been engaging the relevant government officials to relocate the community to safer places. In the short term Zimplats engages the settlers through quarterly liaison meetings and mock drills of TSF failure to sensitise them on the actions to be taken in the event of TSF failure early warnings.			
Surrounding environment analysis			
30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	No		
31. Seismicity rating of the TMF's location.	Low seismic region with peak ground acceleration of 0.2m/s ²		
32. Do current neighboring mining operations include blasting?	No mines close by are decommissioned		
a. If yes, distance of the TMF to the mining operations.			



ZIMPLATS

Disclosure Requirements	Zimplats
Tailings Facility Name and Identifier	Sellous Metallurgical ComplexTSF Extension
Location	18° 0' 36", 30° 4' 34"

1 Company name	Zimplats	For an operational and closed facilities	
2 Company's membership with ICMM or other international industry body.	No	16 Year construction was started.	Not applicable. SMC TSF Extension not yet constructed. Motivation for construction under review pending approvals
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?	Yes	17 Current tailings production (ktpy).	
a. Are audit reports (external and/or internal) shared with the board?	Yes	18 Current density/water content of the tailings being deposited.	
		19 Expected remaining years of operations.	
4 Number of TMFs owned by the company		TMF Monitoring	
a. In construction?	SMC TSF extension construction motivation under review for approvals	20 Frequency of internal inspections (if any)	Not applicable. TSF not yet constructed
b. In operation?	2	a. Date of last internal inspection including outcome.	Not applicable
c. Closed/decommissioned?	Nil	21 Is there a requirement for external inspections?	Yes
d. In operation/closed but not decommissioned/decommissioned?	Nil	a. Frequency of external inspections.	Every 4 months by TSF designers and every two years by independent third party
For Each TMF		b. Name of external firm that performs the inspection.	SRK designed the SMC TSF extension and SLR performed the third-party review on the design
5 Mine name	18° 0' 36", 30° 4' 34"	c. Date of last external inspection including outcome.	Not applicable, Not yet constructed.
6 Location (Country/State/Municipality)	Zimbabwe/Mashonaland West Province/Selous	22 If there is an external rating system (i.e. local regulator),	No external rating.
7 TMF name or designation	SMC	a. What is the risk rating for the TMF?	Not applicable
8 Location of Facility (lat/long or position relative to the main mine facilities)	18° 0' 36", 30° 4' 34"	For TMF with embankment retaining structures	
9 The types of commodities being mined	Platinum Group Metals	Design	
10 What are the main methods used in the processing of the ore prior to deposition.	Milling and Flotation	23 Type of construction	
11 How are the tailings stored? (conventional, thickened, paste, dry stack, other)	Conventional	a. Upstream, downstream, centerline, other;	Proposed design of upstream
12 Do the contents of the TMF include toxic materials?	No	b. Is it constructed on flat ground or on a slope?	Proposed footprint on slightly sloppy ground with a kopje on northern tip of footprint
For a decommissioned facility		c. Does it include a spillway or other structure to mitigate overtopping?	Designed with berms on the outer paddocks to mitigate overtopping
13 Year construction was started.	N/A	d. Does it include an overdrain and/or underdrain system?	Underdrains included in the design
14 Last year that material was added to the facility.	N/A	24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/CDA), ANCOLD, ICOLD or others?	SANS 10286 and ANCOLD
15 Year of decommissioning.	N/A		
a. Was it capped, crowned and/or was another method used to reduce water infiltration?	N/A		
b. Frequency of internal/external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	N/A		



ZIMPLATS

Disclosure Requirements	Zimplats
Tailings Facility Name and Identifier	Sellous Metallurgical ComplexTSF Extension
Location	18° 0' 36", 30° 4' 34"

		Additional comments incl. mitigants
25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	Designed for stability of drained FoS 1.85 (target ≥ 1.5) and undrained FoS 1.52 (target ≥ 1.3)	The SMC TSF extension footprint resides illegal settlers who are in court wrangle with the rightful farm owner. Preliminary court verdict was in favour of the rightful farm owner to evict the illegal settlers. Case is pending finalisation at the courts.
26. Current dimensions of main structure, including height, upstream slope and downstream slope.	Designed to abut to existing facility and to reach maximum elevation of 1298meters above mean sea level (mamsl). Downstream the combined TSFs maximum height shall be 56m high.	
27. Planned final dimensions of main structure.	93.3ha (extension) and 203ha combined abutting TSFs. Maximum elevation of 1298mamsl.	
28. Current volume of tailings facility (m³, tonnes, etc.).	Not yet constructed but designed to contain 49.7 million tonnes (portion to extension facility)	
29. Planned final volume of tailings facility.	31.1m ³ (portion to extension facility)	
Surrounding environment analysis		
30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	No	
31. Seismicity rating of the TMF's location.	Low seismic region with peak ground acceleration of 0.2m/s	
32. Do current neighboring mining operations include blasting?	No. Mines close by are decommissioned	
a. If yes, distance of the TMF to the mining operations.		
33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	9 illegal settlers (families) residing in the SMC extension footprint	
34. Nearest critical infrastructure downstream from the facility, including nearby TMFs.	Community homesteads and three bridges.	





ZIMPLATS


Disclosure Requirements	Zimplats
Tailings Facility Name and Identifier	Mhondoro Ngezi TSF
Location	18°20'33.0"S 30°12'06.1"E


1 Company name	Zimplats	a. Was it capped, crowned and/or was another method used to reduce water infiltration?	N/A
2 Company's membership with ICMM or other international industry body.	No	b. Frequency of internal/external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	N/A
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?	Yes, Continuous daily monitoring by a contracting company (Fraser Alexander) employees, triannual inspections by Geotechnical engineers (SRK), bi-ennial inspections by an independent consultant	For an operational and closed facilities	
a. Are audit reports (external and/or internal) shared with the board?	Yes	16 Year construction was started.	2009
4 Number of TMFs owned by the company		17 Current tailings production (ktpy).	4270
a. In construction?	Nil	18 Current density/water content of the tailings being deposited.	Slurry sg of 1.55
b. In operation?	1	19 Expected remaining years of operations.	84 years
c. Closed/decommissioned?	Nil	TMF Monitoring	
d. In operation/closed but not decommissioned/decommissioned?	1	20 Frequency of internal inspections (if any)	Weekly and monthly inspection by operator's management and tri-annual and annual inspections by designers (Geotechnical Engineers) SRK
For Each TMF		a. Date of last internal inspection including outcome.	Monthly inspection of December 2020, Triannual inspection of November 2020
5 Mine name	Zimbabwe Platinum Mines	21 Is there a requirement for external inspections?	Yes
6 Location (Country/State/Municipality)	Zimbabwe, Mhondoro Ngezi	a. Frequency of external inspections.	Biannual
7 TMF name or designation	Zimplats - Ngezi Concentrator TSF	b. Name of external firm that performs the inspection.	Changes regularly (Used Ken Lyell Consulting (2018), have engaged LRS Consulting for the next inspection)
8 Location of Facility (lat/long or position relative to the main mine facilities)	Latitude 18° 34' 25" Longitude 30° 20' 17"	c. Date of last external inspection including outcome.	(Scheduled inspection in November 2018 by Ken Lyell followed by a one inspection in December 2019 by John Wates). Both inspections found the facility complying to design requirements and being operated according to best practice.
9 The types of commodities being mined	Platinum Group Metals, Nickel and Copper	22 If there is an external rating system (i.e. local regulator),	No
10 What are the main methods used in the processing of the ore prior to deposition.	Crushing and grinding of ore followed by bulk sulphide flotation	a. What is the risk rating for the TMF?	Not applicable
11 How are the tailings stored? (conventional, thickened, paste, dry stack, other)	Thickened before upstream conventional deposition using a hybrid of paddock and open spigot deposition method		
12 Do the contents of the TMF include toxic materials?	No		
For a decommissioned facility			
13 Year construction was started.	N/A		
14 Last year that material was added to the facility.	N/A		
15 Year of decommissioning.			



ZIMPLATS

Disclosure Requirements	Zimplats
Tailings Facility Name and Identifier	Mhondoro Ngezi TSF
Location	18°20'33.0"S 30°12'06.1"E

For TMF with embankment retaining structures		33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	Current Population At Risk is limited to people working on the dam only.
Design			
23. Type of construction		Additional comments incl. mitigants	
a. Upstream, downstream, centerline, other;	Upstream	<p>The SMC TSF extension footprint resides illegal settlers who are in court wrangle with the rightful farm owner. Preliminary court verdict was in favour of the rightful farm owner to evict the illegal settlers. Case is pending finalisation at the courts.</p> 	
b. Is it constructed on flat ground or on a slope?	Relatively inclined		
c. Does it include a spillway or other structure to mitigate overtopping?	No		
d. Does it include an overdrain and/or underdrain system?	Underdrain system		
24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/CDA), ANCOLD, ICOLD or others?	SANS 10286:1998		
25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	Drained overall FoS is 1.71 minimum (design 1.50), Undrained FoS is 1.40 minimum (Design 1.2)		
26. Current dimensions of main structure, including height, upstream slope and downstream slope.	12m high with a 1V:3H overall slope		
27. Planned final dimensions of main structure.	96m high with top area of 291Ha		
28. Current volume of tailings facility (m³, tonnes, etc.).	23.6million m³		
29. Planned final volume of tailings facility.	296 million m³		
Surrounding environment analysis			
30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	No		
31. Seismicity rating of the TMF's location.	Low 0 – 0.2 m/s²		
32. Do current neighboring mining operations include blasting?	Yes. Underground blasting		
a. If yes, distance of the TMF to the mining operations.	5km		



LAC DES ILES

Disclosure Requirements	Impala Canada - Lac des Iles
Tailings Facility Name and Identifier	Impala Canada – Lac des Iles
Location	89°39'01.06"W / 49°09'07.68" N


1 Company name	Impala Canada – Lac des Iles	For a decommissioned facility	
2 Company's membership with ICMM or other international industry body.	No	13 Year construction was started.	N/A
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?	Yes	14 Last year that material was added to the facility.	N/A
a. Are audit reports (external and/or internal) shared with the board?	Not usually, but are upon request	15 Year of decommissioning.	N/A
4 Number of TMFs owned by the company		a. Was it capped, crowned and/or was another method used to reduce water infiltration?	N/A
a. In construction?	0	b. Frequency of internal/external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	N/A
b. In operation?	2	For an operational and closed facilities	
c. Closed/decommissioned?	1	16 Year construction was started.	2010
d. In operation/closed but not decommissioned/decommissioned?	0	17 Current tailings production (ktpy).	12,500 tonnes per day
For Each TMF		18 Current density/water content of the tailings being deposited.	50% solids content
5 Mine name	Lac des Iles Mine	19 Expected remaining years of operations.	Four (4)
6 Location (Country/State/Municipality)	Thunder Bay, Ontario, Canada	TMF Monitoring	
7 TMF name or designation	South Tailings Management Facility (STMF)	20 Frequency of internal inspections (if any)	
8 Location of Facility (lat/long or position relative to the main mine facilities)	STMF = 89°39'01.06"W/49°09'07.68" N	a. Date of last internal inspection including outcome.	Performed Daily. No problems detected.
9 The types of commodities being mined	Mostly palladium, with some platinum and traces of gold, copper and nickel.	21 Is there a requirement for external inspections?	
10 What are the main methods used in the processing of the ore prior to deposition.	Drilling, Blasting, hauling, crushing, grinding, flotation	a. Frequency of external inspections.	Dam Safety Inspection (DSI) on a yearly basis. Dam Safety Review (DSR) every 5 years or upon significant change.
11 How are the tailings stored? (conventional, thickened, paste, dry stack, other)	Thickened	b. Name of external firm that performs the inspection.	DSIs carried out by Hatch Ltd (Engineer of Record). Last DSR carried out by Knight-Piesold, but may vary in future.
12 Do the contents of the TMF include toxic materials?	No	c. Date of last external inspection including outcome.	Last DSI carried out in October 2020. Last DSR also carried out in October 2020.



LAC DES ILES

Disclosure Requirements	Impala Canada - Lac des Iles
Tailings Facility Name and Identifier	Impala Canada – Lac des Iles
Location	89°39'01.06"W / 49°09'07.68" N


22 If there is an external rating system (i.e. local regulator),	Technical Bulletin - Classification and Inflow Design Flood Criteria" of the Lakes and River Improvement Act (LRIA) (Ontario Ministry of Natural Resources, 2011a)	Surrounding environment analysis	
a. What is the risk rating for the TMF?	High, for incremental environmental losses.	30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	No
For TMF with embankment retaining structures		31. Seismicity rating of the TMF's location.	The LDI Mine site is in a stable seismic zone, with a peak maximum credible (2,500 yr return period) seismic ground acceleration of 0.040 g.
Design		32. Do current neighboring mining operations include blasting?	No neighboring mining operations.
23 Type of construction	Hybrid upstream and downstream	a. If yes, distance of the TMF to the mining operations.	
a. Upstream, downstream, centerline, other;		33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	The inundation area is typically undeveloped or it is managed so that the land usage is for transient activities such as with day-use facilities. Appreciable loss of fish and/or wildlife habitat or significant deterioration of critical fish and/ or wildlife habitat with reasonable likelihood of being able to apply natural or assisted recovery activities to promote species recovery to viable population levels.
b. Is it constructed on flat ground or on a slope?	Mainly flat ground.	34. Nearest critical infrastructure downstream from the facility, including nearby TMFs.	Water Management Facility 1, which is the central facility for collecting contact water from entire mine site, including TMFs.
c. Does it include a spillway or other structure to mitigate overtopping?	Yes, spillway included	Additional comments incl. mitigants	
d. Does it include an overdrain and/or underdrain system?	Yes, underdrain in foundation of upstream raise embankments.		
24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/ CDA), ANCOLD, ICOLD or others?	Technical Bulletin - Classification and Inflow Design Flood Criteria" of the Lakes and River Improvement Act (LRIA) (Ontario Ministry of Natural Resources, 2011a), MAC, CDA		
25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	Current conditions FoS = 1.5, worst-case (Inflow Design Flood conditions) FoS = 1.3		
26. Current dimensions of main structure, including height, upstream slope and downstream slope.	22.5 m in height, downstream slope (rockfill) 1.5H:1V, upstream slope of 2.5H:1V		
27. Planned final dimensions of main structure.	26 m in final height.		
28. Current volume of tailings facility (m ³ , tonnes, etc.).	13,496,000 m ³		
29. Planned final volume of tailings facility.	19,739,000 m ³		



LAC DES ILES

Disclosure Requirements	Impala Canada - Lac des Iles
Tailings Facility Name and Identifier	East Tailings Management Facility (ETMF)
Location	89°37'07.65"W / 49°09'06.53" N


1 Company name	Impala Canada – Lac des Iles	For a decommissioned facility	
2 Company's membership with ICMM or other international industry body.	No	13 Year construction was started.	N/A
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?		14 Last year that material was added to the facility.	N/A
a. Are audit reports (external and/or internal) shared with the board?		15 Year of decommissioning.	N/A
4 Number of TMFs owned by the company		a. Was it capped, crowned and/or was another method used to reduce water infiltration?	N/A
a. In construction?		b. Frequency of internal/external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	N/A
b. In operation?		For an operational and closed facilities	
c. Closed/decommissioned?		16 Year construction was started.	1992
d. In operation/closed but not decommissioned/decommissioned?		17 Current tailings production (ktpy).	12,500 tonnes per day
For Each TMF		18 Current density/water content of the tailings being deposited.	50% solids content
5 Mine name	Lac des Iles Mine	19 Expected remaining years of operations.	five (5)
6 Location (Country/State/Municipality)	Thunder Bay, Ontario, Canada	TMF Monitoring	
7 TMF name or designation	East Tailings Management Facility (ETMF)	20 Frequency of internal inspections (if any)	
8 Location of Facility (lat/long or position relative to the main mine facilities)	ETMF = 89°37'07.65"W/49°09'06.53" N	a. Date of last internal inspection including outcome.	Performed Daily. No problems detected.
9 The types of commodities being mined	Mostly palladium, with some platinum and traces of gold, copper and nickel.	21 Is there a requirement for external inspections?	
10 What are the main methods used in the processing of the ore prior to deposition.	Drilling, Blasting, hauling, crushing, grinding, flotation	a. Frequency of external inspections.	Dam Safety Inspection (DSI) on a yearly basis. Dam Safety Review (DSR) every 5 years or upon significant change
11 How are the tailings stored? (conventional, thickened, paste, dry stack, other)	Thickened	b. Name of external firm that performs the inspection.	DSIs carried out by Hatch Ltd (Engineer of Record). Last DSR carried out by Knight-Piesold, but may vary in future.
12 Do the contents of the TMF include toxic materials?	No	c. Date of last external inspection including outcome.	Last DSI carried out in October 2020. Last DSR also carried out in October 2020.



LAC DES ILES

Disclosure Requirements	Impala Canada - Lac des Iles
Tailings Facility Name and Identifier	East Tailings Management Facility (ETMF)
Location	89°37'07.65"W / 49°09'06.53" N


22 If there is an external rating system (i.e. local regulator),	Technical Bulletin - Classification and Inflow Design Flood Criteria" of the Lakes and River Improvement Act (LRIA) (Ontario Ministry of Natural Resources, 2011a)	Surrounding environment analysis	
a. What is the risk rating for the TMF?	High, for incremental environmental losses.	30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	No
For TMF with embankment retaining structures		31. Seismicity rating of the TMF's location.	The LDI Mine site is in a stable seismic zone, with a peak maximum credible (2,500 yr return period) seismic ground acceleration of 0.040 g.
Design		32. Do current neighboring mining operations include blasting?	No neighboring mining operations.
23 Type of construction		a. If yes, distance of the TMF to the mining operations.	
a. Upstream, downstream, centerline, other;	Hybrid upstream and downstream.	33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	The inundation area is typically undeveloped or it is managed so that the land usage is for transient activities such as with day-use facilities. Appreciable loss of fish and/or wildlife habitat or significant deterioration of critical fish and/ or wildlife habitat with reasonable likelihood of being able to apply natural or assisted recovery activities to promote species recovery to viable population levels.
b. Is it constructed on flat ground or on a slope?	Mainly flat ground.	34. Nearest critical infrastructure downstream from the facility, including nearby TMFs.	Water Management Facility 1, which is the central facility for collecting contact water from entire mine site, including TMFs.
c. Does it include a spillway or other structure to mitigate overtopping?	Yes, spillway included	Additional comments incl. mitigants	
d. Does it include an overdrain and/or underdrain system?	Yes, underdrain in foundation of upstream raise embankments.		
24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/ CDA), ANCOLD, ICOLD or others?	Technical Bulletin - Classification and Inflow Design Flood Criteria" of the Lakes and River Improvement Act (LRIA) (Ontario Ministry of Natural Resources, 2011a), MAC, CDA		
25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	Current conditions FoS = 1.5, worst-case (Inflow Design Flood conditions) FoS = 1.3		
26. Current dimensions of main structure, including height, upstream slope and downstream slope.	23.0 m in height, downstream slope (rockfill) 1.5H:1V, upstream slope of 2.5H:1V.		
27. Planned final dimensions of main structure.	26.5 m in final height.		
28. Current volume of tailings facility (m ³ , tonnes, etc.).	9,226,000 m ³		
29. Planned final volume of tailings facility.	19,096,000 m ³		



LAC DES ILES

Disclosure Requirements	Impala Canada - Lac des Iles
Tailings Facility Name and Identifier	West Tailings Management Facility (WTMF)
Location	89°38'00.92"W / 49°09'21.39" N

1 Company name	Impala Canada – Lac des Iles	For a decommissioned facility	
2 Company's membership with ICMM or other international industry body.	No	13 Year construction was started.	2001
3 Does the company have an internal monitoring set-up specific to Tailings Management Facilities (TMFs)?		14 Last year that material was added to the facility.	2011
a. Are audit reports (external and/or internal) shared with the board?		15 Year of decommissioning.	2012 and 2015
4 Number of TMFs owned by the company		a. Was it capped, crowned and/or was another method used to reduce water infiltration?	Only a vegetative cover was installed, with no ability to reduce water infiltration.
a. In construction?		b. Frequency of internal/external inspections of an TMF after decommissioning for monitoring safety and environmental impacts.	Daily by site personnel. Dam Safety Inspection (DSI) on a yearly basis. Dam Safety Review (DSR) every 5 years or upon significant change.
b. In operation?		For an operational and closed facilities	
c. Closed/decommissioned?		16 Year construction was started.	2001
d. In operation/closed but not decommissioned/decommissioned?		17 Current tailings production (ktpy).	Closed, not applicable
For Each TMF		18 Current density/water content of the tailings being deposited.	Closed, not applicable
5 Mine name	Lac des Iles Mine	19 Expected remaining years of operations.	0
6 Location (Country/State/Municipality)	Thunder Bay, Ontario, Canada	TMF Monitoring	
7 TMF name or designation	West Tailings Management Facility (WTMF)	20 Frequency of internal inspections (if any)	Daily
8 Location of Facility (lat/long or position relative to the main mine facilities)	WTMF = 89°38'00.92"W/49°09'21.39" N	a. Date of last internal inspection including outcome.	Performed Daily. No problems detected.
9 The types of commodities being mined	Mostly palladium, with some platinum and traces of gold, copper and nickel.	21 Is there a requirement for external inspections?	
10 What are the main methods used in the processing of the ore prior to deposition.	Drilling, Blasting, hauling, crushing, grinding, flotation	a. Frequency of external inspections.	Dam Safety Inspection (DSI) on a yearly basis. Dam Safety Review (DSR) every 5 years or upon significant change.
11 How are the tailings stored? (conventional, thickened, paste, dry stack, other)	Thickened	b. Name of external firm that performs the inspection.	DSIs carried out by Hatch Ltd (Engineer of Record). Last DSR carried out by Knight-Piesold, but may vary in future.
12 Do the contents of the TMF include toxic materials?	No	c. Date of last external inspection including outcome.	Last DSI carried out in October 2020. Last DSR also carried out in October 2020.



LAC DES ILES

Disclosure Requirements	Impala Canada - Lac des Iles
Tailings Facility Name and Identifier	East Tailings Management Facility (ETMF)
Location	89°37'07.65"W / 49°09'06.53" N

22 If there is an external rating system (i.e. local regulator),	Technical Bulletin - Classification and Inflow Design Flood Criteria" of the Lakes and River Improvement Act (LRIA) (Ontario Ministry of Natural Resources, 2011a)	Surrounding environment analysis	
a. What is the risk rating for the TMF?	Moderate, for incremental environmental losses.	30. Is the TMF located in a climatic zone where evaporation levels are exceeded by precipitation?	No
For TMF with embankment retaining structures		31. Seismicity rating of the TMF's location.	The LDI Mine site is in a stable seismic zone, with a peak maximum credible (2,500 yr return period) seismic ground acceleration of 0.040 g.
Design		32. Do current neighboring mining operations include blasting?	No neighboring mining operations.
23 Type of construction		a. If yes, distance of the TMF to the mining operations.	
a. Upstream, downstream, centerline, other;	Downstream only	33. Identification of habitation(s)/ settlements(s) and/or flora/ fauna critical habitat(s) or high biodiversity area(s) located downstream of the facility, with indication of areas or number of populations at risk, and the mitigative measures that have been undertaken or remain to be implemented.	The inundation area is typically undeveloped or it is managed so that the land usage is for transient activities such as with day-use facilities. Appreciable loss of fish and/or wildlife habitat or significant deterioration of critical fish and/ or wildlife habitat with reasonable likelihood of being able to apply natural or assisted recovery activities to promote species recovery to viable population levels.
b. Is it constructed on flat ground or on a slope?	Mainly flat ground.	34. Nearest critical infrastructure downstream from the facility, including nearby TMFs.	Water Management Facility 1, which is the central facility for collecting contact water from entire mine site, including TMFs.
c. Does it include a spillway or other structure to mitigate overtopping?	No spillway	Additional comments incl. mitigants	
d. Does it include an overdrain and/or underdrain system?	No		
24. What standards/guidelines were applied to the dam design and construction, i.e. Canadian (MAC/ CDA), ANCOLD, ICOLD or others?	Technical Bulletin - Classification and Inflow Design Flood Criteria" of the Lakes and River Improvement Act (LRIA) (Ontario Ministry of Natural Resources, 2011a), MAC, CDA		
25. What is the "Factor of Safety" (under current conditions and "worst case/undrained conditions")?	Current conditions FoS = 1.5, worst-case (Inflow Design Flood conditions) FoS = 1.3		
26. Current dimensions of main structure, including height, upstream slope and downstream slope.	30.0 m in height, downstream slope (rockfill) 1.5H:1V, upstream slope of 3H:1V.		
27. Planned final dimensions of main structure.	30.0 m in final height.		
28. Current volume of tailings facility (m ³ , tonnes, etc.).	20,070,000 m ³		
29. Planned final volume of tailings facility.	20,070,000 m ³		